

Opel Zafira B - Strømningsstøj | HELLA

Opel Zafira B Årgang: 2005 - Med klimaanlæg Der trænger strømningssøj ind i kabinen, I ovennævnte modeller kan der forekomme støj fra motorrummet ved driftsvarm motor. Det forekommer især ved acceleration og et motoromdrejningstal mellem 2000 og 3000 o/min. Årsagen kan være en manglende eller forkert placeret dæmperstrimmel mellem længdevangen og kølemiddelrøret. Kontroller, at dæmperstrimlen er til stede hhv. er korrekt placeret. Om nødvendigt anbringes der en ny dæmperstrimmel. Kølemiddelrøret må ikke berøre længdevangen. Ellers kan kølemidlets strømningsslyde overføres til kabinen via karrosseriet. Det skal påses, at dæmperstrimlen stikker ca. 5 mm ud over kanten af længdevangen. Bemærk: En velegnet dæmperstrimmel er Hella art.-nr. 9MJ 351 018-011

Zafira B

Model years: 2005 -

With air-conditioning system

Flow noise entering into the passenger compartment

Noise may be coming from the engine compartment in the above vehicles when the engine is running at operating temperature. This occurs in particular during acceleration of the vehicle and an engine speed between 2000 and 3000 rpm.

The cause may be a missing or misplaced damper strip between the frame rail and the refrigerant line.

Make sure that the damping strip is present and correctly installed. If necessary, attach a new damping strip. When doing so, make sure that the refrigerant line does not come into contact with the frame rail.

Otherwise, the flow noise of the refrigerant may be transmitted through the body into the vehicle interior. It is important to ensure that the damping strip extends approx. 5mm beyond the edge of the frame rail.

Note: A suitable damping strip is Hella part no. 9MJ 351 018-011