

PEUGEOT 307 - ABS warning light illuminates | HELLA

Peugeot

Model: 307

All models with ABS/ESP

ABS warning light illuminates

Error code: 21287

Left rear RPM sensor

If the above error is discovered together with an illuminated ABS warning light, this may be due to a cable fracture underneath the heat shield cover for the rear muffler.

In this case, the wiring harness must be checked and repaired if necessary.