



BMW 1 Series - outside mirrors do not fold in when using the remote control

Data sheet

Manufacturer	BMW
Vehicle model	1 Series (F40)
Engine	All models without keyless system
Year of manufacture	2019 -
Symptoms	Mirror folding function/central locking system

Important safety note

The mirrors' folding function is disturbed, and the central locking system is possibly impaired

On the vehicles mentioned above, the outside mirrors may not fold in when the vehicle is locked with the remote control. Furthermore, the locking function may be impaired when using the remote control. A software error in the multi-function control unit could be causing the problem. To remedy this, the vehicle battery and the vehicle electrical system voltage should be checked beforehand. If another remote key exists, check whether the function works when using it. In addition, the error memories must be read out and, if necessary, deleted. If this does not lead to the desired outcome, a software update can be carried out on the multi-function control unit to eliminate the problem. A software update can be carried out, for example, via Hella-Gutmann macsRemote Services or a PassThru-capable diagnostic device from the mega macs series. Furthermore, registered access to the vehicle manufacturer's online portal is required. If the appropriate equipment is not available, please contact an authorised specialist workshop.



Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval; indication of the document source is also required. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.