

# Mitsubishi Grandis - Brake light switch failure | HELLA

**Mitsubishi**

**Grandis**

**Model year: 02/2004 to 03/2008**

**Engine: 2.0 16V Di-D / 2.4i 16V**

## **Brake light switch failure**

If a complaint is made about the TSC lamp ("Traction control") and/or the ASC lamp ("Active stability control") lighting up in the above vehicle, this may indicate a faulty brake light switch.

A faulty silicone seal can lead to moisture getting into the brake light switch.

This moisture can lead to a malfunction or complete failure of the brake light switch.

The vehicle manufacturer has already addressed the issue.

The brake light switch should be checked, and replaced with a modified brake light switch if necessary, in the specialist workshop.