



Porsche Macan (95B) - Clicking noises in the interior

Data sheet	
Manufacturer	Porsche
Vehicle model	Macan (95B)
Engine	All models
Year of manufacture	2014 - 02/2016
Symptoms	Clicking noises in the interior

Important safety note

Clicking noises from the A-pillar or instrument panel area

If non-specific noises occur in the area of the A-pillar or instrument panel on the vehicles mentioned above, they may be caused by the bonnet rubber stoppers.

<shy /> To remedy this, the bonnet's rear rubber stoppers should be replaced by a modified version:

<shy /> Right/left stopper: 95B.863.238A / 95B.863.237A

Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval; indication of the document source is also required. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.