

Hyundai IX 35 - Le moteur ne démarre pas | HELLA

Hyundai

IX 35

Année de fabrication: 03/2011

Le moteur ne démarre pas

Le démarreur ne fonctionne pas

Aucune erreur dans le calculateur

En cas de détection du problème susnommé, un commutateur défectueux au niveau de la pédale d'embrayage peut être en cause.




Fig. 3



Fig. 1




Fig. 2

Important safety notice

The following technical information and tips for practical use have been set up by HELLA in order to offer professional support to automotive workshops in their daily work. The information available here on this website is only to be used by appropriately trained specialist staff.

The reprinting, distribution, reproduction, exploitation in any form and disclosure of the contents of this document, even in part, is prohibited without our express written approval and indication of the source. The schematic illustrations, figures and descriptions are for explanation and presentation of the document text and cannot be used as a basis for installation or design. All rights reserved.