

MERCEDES Classe C - Allumage du témoin d'ESP/ABS | HELLA

MERCEDES


Classe C (W 203)

Tous les véhicules à partir de l'année modèle 02.03

Allumage du témoin d'ESP/ABS

Si un client signale le problème mentionné ci-dessus, un connecteur corrodé peut être en cause. Il peut en outre également y avoir les codes d'erreur C1140 (capteur d'angle du volant, signal erroné) ou C1145 (capteur ABS de vitesse de rotation de roue AD, interruption).

31



17

Important safety note

The following technical information and tips for practical use have been set up by HELLA in order to offer professional support to automotive workshops in their daily work. The information available here on this website is only to be used by appropriately trained specialist staff.

The reprinting, distribution, reproduction, exploitation in any form and disclosure of the contents of this document, even in part, is prohibited without our express written approval and indication of the source. The schematic illustrations, figures and descriptions are for explanation and presentation of the document text and cannot be used as a basis for installation or design. All rights reserved.