

Citroen C4 - ESP/ABS pilot lamp lights up | HELLA

Citroen

All left-hand drive models

Model years to 06/2008

ESP/ABS pilot lamp lights up

If a customer complains about the above error, this could be caused by the brake pedal position sensor. Various problems may also occur with cruise control, such as:

