



Nissan Qashqai (J11) - sporadic triggering of the alarm system

Data sheet	
Manufacturer	Nissan
Vehicle model	Qashqai (J11)
Engine	All models
Year of manufacture	2014 - 2021
Symptoms	Sporadic triggering of the alarm system

Important safety note

Nissan Qashqai (J11) - sporadic triggering of the alarm system

With the above-mentioned vehicle, it may happen that the vehicle interior monitoring system, every so often, triggers the vehicle alarm. A faulty ultrasonic sensor of the vehicle interior's lamp unit is a possible cause.

In order to rule out any other causes, please check all relevant system components and read out the error memory.

If no errors are detected, it is recommended to replace the sensor of the vehicle interior monitoring system. This is located in the lamp unit of the vehicle interior.

Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval; indication of the document source is also required. The schematic illustrations, pictures and descriptions serve only

for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.