

Opel Astra-G, Opel Zafira, Vectra-B - Irregular engine running | HELLA

Opel Astra-G, Vectra-B

Model years 1998-2000

Opel Zafira

Model years 1999-2000

All models with X18XE1 engine

All models with X18XE1 engine

If the above-mentioned symptoms occur on these vehicles, this may be caused by a dirty throttle valve. In this case, check the blow-by hole and, if necessary, drill open to 2mm. Afterwards, the ECU must be reprogrammed with a software modified for this purpose. The ECU software can only be updated by an authorised dealer.



