

Alfa Romeo 147 (Type 937) - ESP-kontrollampen lyser periodisk | HELLA

Alfa Romeo 147 (Type 937) Alle modeller VIN 3327094-3354034 VIN 5213889-5234805 Elektronisk Stabilitets-Program (ESP) reagerer for følsomt ESP-kontrollampen lyser periodisk Hvis det konstateres, at ESP-systemet griber for tidligt ind, kan årsagen være en fejlagtig softwarebearbejdning i styreenheden. I så fald kontrolleres først spændingstilførslen og periferikomponenterne i ABS/ESP-systemet. Hvis alle testresultater svarer til de foreskrevne værdier, udskiftes ABS/ESP-styreenheden. Reparationsanvisning I nogle tilfælde er det muligt at opdatere softwaren. I så fald skal man henvende sig til en autoriseret forhandler.

147 (Type 937)

All models

VIN 3327094-3354034

VIN 5213889-5234805

Electronic Stability Program (ESP) too sensitive

ESP indicator lamp lights up sporadically

If the ESP system is activating too early, this may be due to faulty software evaluation in the control unit.

First of all, check the power supply and the peripheral equipment of the ABS/ESP system. If all the test results correspond to the targets, the ABS/ESP control unit is the probable cause and should be replaced.

Repair note

In some cases, it may be possible to update the software. If this is the case, please contact an authorized dealer.