

Alfa Romeo 159 (Type 939) - Fejlkode C1275 | HELLA

Alfa Romeo 159 (Type 939) Alle modeller indtil VIN 7097552
ESP-kontrollampen lyser Fejlkode C1275
ABS-magnetventil Hvis ovennævnte fejlkode forekommer samtidig med, at ABS-kontrollampen lyser, kan årsagen være en fejlagtig softwarebearbejdning i styreenheden. I så fald kontrolleres først spændingstilførslen og periferikomponenterne i ABS/ESP-systemet. Hvis alle testresultater svarer til de foreskrevne værdier, udskiftes ABS/ESP-styreenheden. Reparationsanvisning
I nogle tilfælde er det muligt at opdatere softwaren. I så fald skal man henvende sig til en autoriseret forhandler.

159 (Type 939)

All models up to VIN 7097552

ESP indicator lamp lights up

Error code C1275

ABS solenoid valve

If the error code listed above is discovered together with an illuminated ABS indicator lamp, this may be due to faulty software evaluation in the control unit.

First of all, check the power supply and the peripheral equipment of the ABS/ESP system. If all the test results correspond to the targets, the ABS/ESP control unit is the probable cause and should be replaced.

Repair note

In some cases, it may be possible to update the software. If this is the case, please contact an authorized dealer.