

# BMW i3 (I01) - Fejl i radiomodtagelse | HELLA

**BMW**

**i3 (I01)**

**Årgang: 2013**

## **Fejl i radiomodtagelse**

I denne reparationssituation klager kunden over, at radiomodtagelsen ikke virker eller er fejlbehæftet.

Fejlfinding:

En udlæsning af fejlkodehukommelsen med en egnet tester viste, at der ikke er gemt fejkoder.

Ved nærmere betragtning af tagantenneenheden viste det sig, at antennestangen er beskadiget (revne i eller brud på gevindstangen), hvilket er årsagen til det ovennævnte problem.

Afhjælpning:

- Afmonter antennestangen.
- Kontrollér gevindet på antennestangen (se foto) samt gevindgangen i tagantenneenheden med henblik på beskadigelser, og reparer eller udskift evt.
- Montér den nye antennestang.
- Kontrollér radioens funktion.



**Højspændingsførende komponenter - der er fare for ulykker og kvæstelser (elektrisk stød)!**

img src="[ioID]FD52A93DEAE5405198C100C5F0BF8F87/bi\_da\_car-body\_bmw-i3\_antennenstab-gebrochen001.jpg" alt="" class="img-responsive withoutBorder" />

## **Important safety notice**

The following technical information and tips for practical use have been set up by HELLA in order to offer professional support to automotive workshops in their daily work. The information available here on this website is only to be used by appropriately trained specialist staff.

The reprinting, distribution, reproduction, exploitation in any form and disclosure of the contents of this document, even in part, is prohibited without our express written approval and indication of the source. The schematic illustrations, figures and descriptions are for explanation and presentation of the document text and cannot be used as a basis for installation or design. All rights reserved.