

Chevrolet Cruze - Ekspansionsbeholder / Tab af kølevæske | HELLA

ChevroletCruzeÅrgang: 2011 - 2014Motor: 2,0 CDiEkspansionsbeholder / Tab af kølevæske i ovennævnte modeller kan der ske tab af kølevæske som følge af revner ved returstudsen i ekspansionsbeholderen.Revnerne skyldes termisk belastning og kan medføre tab af kølevæske. En heraf følgende forøget motortemperatur indikeres visuelt og akustisk i instrumentgruppen. Evt. går motoren i „nødfunktion“.Afhjælpning sker ved at kontrollere og om nødvendigt udskifte ekspansionsbeholderen.

Cruze

Model year: 2011 - 2014

Motor: 2.0 CDi

Expansion tank/Loss of coolant

Due to cracks in the expansion tank return nozzle, a loss of coolant may be experienced in the above vehicles.

These cracks are caused by thermal loads and may lead to a loss of coolant. If the engine temperature increases as a result of this, acoustic and visual signals will be issued accordingly by the instrument cluster. If necessary, the engine will switch to "emergency running."

In order to remedy the problem, the expansion tank should be checked and, if necessary, replaced.

