

Citroën C3 Pluriel (HB) - Klimaanlæg har nedsat ydelse | HELLA

Citroën C3 Pluriel (HB) Nedsat ydelse af klimaanlæg For højt systemtryk. Hvis klimaanlæggets ydelse er nedsat i ovennævnte modeller, kan årsagen være en defekt kondensator. Kondensatorens lameller kan løsne sig og falde ud som følge af korrosion og/eller vibrationer (se fig.). Det nedsætter kondenseringen af kølemidlet i kondensatoren og kan medføre for højt tryk på højtrykssiden. Afhjælpning sker ved at udskifte kondensator og tørrefilter.

C3 Pluriel (HB)

Poor air-conditioning system performance

System pressure too high.

If customers complain about the air-conditioning system performance on the vehicles mentioned above, the cause may be a faulty condenser.

Corrosion and/or vibrations can cause the condenser fins to come loose and fail (see figure). This impairs the liquefaction of the refrigerant in the condenser and can result in excessive pressure on the high-pressure side.

To eliminate this problem, the condenser and dryer should be replaced.

