

HYUNDAI IX35 - Engine control lamp illuminates | HELLA

HYUNDAI

Model year: 2010

Misfiring, error rate P0301

Misfiring, error rate P0301

On the above mentioned vehicles the engine may misfire resulting in the "jerking" of the engine.

