

Jeep Commander - Fejl ved recirkulationsspjældet | HELLA

Jeep Commander Årgang: 2006 Med manuelt klimaanlæg Funktionsfejl ved recirkulationsspjæld AC-knappen blinker Ved de ovennævnte køretøjer AC-knappens funktionsindikator (billedet) pludseligt begynde at blive ved højere hastigheder. Desuden åbnes og lukkes recirkulationsspjældet hele tiden, hvilket bemærkes ved en knirkende lyd. Fejlen skyldes i dette tilfælde ikke recirkulationssystemet men ligger i spjældstyringen. Problemet kan ofte løses ved at udskifte betjeningsenheden (billedet).

Commander

Model year: 2006

With manual air-conditioning system

Recirculation air flap malfunction

Flashing AC button

With the above vehicles the function indicator of the AC button (Figure) may suddenly start flashing at higher speeds. In addition, the recirculation air flap is repeatedly opened and closed, often noticeable by a squeaking noise.

In this case the fault should not be sought in the recirculation air system, but the flap control. Replacement of the control unit (Figure) can often rectify the problem.



Figure