

# **KIA Sorento - Stoplyset på påhængskøretøjet aktiveres ikke ved bremsning med den trækkende bil | HELLA**

**KIASorento Årgang: 03/2015 - 05/2016 Med adaptiv fartpilot Stoplyset på påhængskøretøjet aktiveres ikke ved bremsning med den trækkende bil Hvis ovenstående fejl konstateres, når fartpiloten (tempomat) er aktiveret, kan det skyldes en defekt påhængsstyreenhed. Bemærk: Problemet forekommer kun under kørsel med tempomat ved automatisk opbremsning, der aktiveres af den adaptive fartpilot. Hvis vogntoget afbremses normalt (via bremsepedalen), forekommer funktionsfejlen ikke! En softwarefejl i påhængsstyreenheden medfører, at stoplyset på påhængskøretøjet ikke aktiveres under de ovennævnte betingelser. Afhjælpning: Påhængsstyreenheden skal udskiftes med en forbedret version iht. fabrikantens anvisninger. I så fald skal man henvende sig til et autoriseret værksted. Bilfabrikanten har allerede taget sig af problemet, og brugerne af de berørte biler er underrettet. Man må dog af diverse grunde gå ud fra, at ikke alle biler er blevet kontrolleret eller udbedret.**

## **Sorento**

**Model Year: 03/2015 – 05/2016**

**With adaptive cruise control**

**Trailer stop light is not controlled by the towing vehicle when brakes are applied**

If the problem described above is determined in conjunction with an activated cruise control system (Tempomat), the cause could be a faulty trailer control module.

Notes:

The problem is only evident when driving with Tempomat during automatic braking triggered by the adaptive cruise control system. If brakes are applied manually (brake pedal) to the vehicle which is towing and to that which is being towed, the malfunction does not occur.

Because of a software error in the trailer control module, the trailer stop lights cannot be controlled in the relevant, above-mentioned situation.

Remedy:

Replace the trailer control module with an improved version as per manufacturer's specifications. In such a case, contact an authorized specialist workshop.

The vehicle manufacturer has already addressed the issue and notified the owners of all the models concerned. For various reasons, however, it must be assumed that not all vehicles have been checked or rectified.