

Lexus IS 200 / 200 D, IS 250, IS 250 C - Fejl ved forrudeviskerne | HELLA

Lexus IS 200 / 200 D Årgang: 06/2005 - 09/2011 IS 250 Årgang: 07/2005 - 09/2011 IS 250 C Årgang: 12/2008 - 09/2011 Viskerne fungerer ikke Hvis ovenstående fejl konstateres, kan det skyldes, at møtrikken til viskerarmen ikke er spændt tilstrækkeligt. Bilfabrikanten har allerede taget sig af problemet, og brugerne af de berørte biler er underrettet. Man må dog af diverse grunde gå ud fra, at ikke alle biler er blevet kontrolleret eller udbedret. I så fald skal man henvende sig til et autoriseret værksted. Her monteres der en forbedret møtrik med det moment, som bilfabrikanten foreskriver (22 Nm).

IS 200 / 200 D

Model Year: 06/2005 – 09/2011

IS 250

Model Year: 07/2005 – 09/2011

IS 250 C

Model Year: 12/2008 – 09/2011

Windshield wiper failure

If the above-mentioned problem occurs, the cause could be insufficient tightening torque of the wiper arm's securing nut.

The vehicle manufacturer has already addressed the issue and notified the owners of all the models concerned. For various reasons, however, it must be assumed that not all vehicles have been checked or rectified.

In such cases, please contact an authorized specialist workshop where an improved securing nut can be fixed according to the tightening torque value (22 NM) specified by the vehicle manufacturer.