

Nissan Pathfinder - Vandindtrængning i kabinen | HELLA

Nissan Pathfinder (R51) Navara (D40) Vandindtrængningen i kabinen i ovennævnte modeller kan ske, at der trænger kondensvand ind i kabinen. Årsagen kan være en for kort afløbsslange til kondensvand. Følgende biler er berørt: Pathfinder (R51), indtil stelnr.: VSK....R51....345825 Navara (D40), indtil stelnr.: VSK....D40....345822 Fejlen afhjælpes på følgende måde: Kontroller afløbet for kondensvand Afmonter evt. slangen til kondensvand, og monter den ændrede version (92590-1F700)

Pathfinder (R51)

Navara (D40)

Water Entering the Vehicle Interior

Condensation may enter the vehicle interiors of the vehicles listed above.

The cause may be that the condensation drain hose is too short.

The following vehicles are affected:

Pathfinder (R51), up to chassis no.: VSK....R51....345825

Navara (D40), up to chassis no.: VSK....D40....345822

Proceed as follows to rectify the problem:

- Check the condensation drain
- If required, remove the condensation hose and install a modified version (92590-1F700)