

Opel Astra J - Utæthed ved kompressor | HELLA

Opel Astra J Årgang: 2010 - 2012 Med klimaanlæg Utæthed ved kompressor I ovennævnte køretøjer kan der opstå utæthed ved kompressoren. Det bemærkes oftest ved udsivning af olie / kontrastmiddel. For at afhjælpe problemet skal kompressoren udskiftes til en ændret version: Gamle res.nr.: Erstatte af nye res.nr. 13 271 264 13 395 696 13 271 266 13 395 693 13 271 267 13 395 694 13 271 268 13 395 695 13 271 269 13 395 696 Fra årgang 2012 benyttes fra fabrikken ændrede kompressorer. Hella kompressorer er uden undtagelse ændret og udviser ikke ovennævnte problem. I tabellen sammenholdes OE- og BHS-nr. til sammenligning. GM GM 133956968 FK 351 340-241 GM 133956948 FK 351 340-251 GM GM Opel Opel Opel Opel Opel Opel Opel Vauxhall Vauxhall Vauxhall Vauxhall Vauxhall Vauxhall Vauxhall

Astra J

Model year: 2010 - 2012

With air-conditioning system

Compressor leakage

The above-mentioned vehicles can experience a compressor leakage. This is mostly noticeable by escaping oil/dye. To fix this problem, the compressor must be exchanged for a modified version:

Old Part No: Replaced By New Part No:

13 271 264 13 395 696

13 271 266 13 395 693

13 271 267 13 395 694