

# Peugeot 306 - Mangelfuld temperaturregulering | HELLA

**Peugeot 306 Årgang: 2002 - 2009** Alle modeller med elektrisk aktiveret blandespjæld **Mangelfuld temperaturregulering** Drev til blandespjæld I nogle af ovennævnte modeller kan der forekomme problemer med styringen af kabinetemperaturen. Årsagen kan være en fejl i motoren til blandespjældet. Der kan være tale om, at drevet hhv. adapterpladen mellem motor og spjæld kan være beskadiget. Det er muligt at genetablere spjældets funktion ved brug af et reparationssæt (drev og adapterplade). Det er ikke nødvendigt at afmontere instrumentbrættet. Alt efter model skal midterkonsollen demonteres/monteres. Efter reparationen skal motoren hhv. spjældstyringen grundindstilles. De nødvendige reservedele og yderligere informationer kan fås hos Peugeot-forhandlerne.

**306**

**Model year: 2002 - 2009**

**All models with an electrically actuated blender flap**

**Defective temperature control**

**Blender flap drive**

Some vehicles of the type listed above may experience problems with interior temperature control.

This could be due to a defect in the blender flap motor. The drive or adapter plate between the motor and the flap may be damaged.

A repair kit (drive and adapter plate) can be used to restore the flap to full functionality. The dashboard does not need to be removed in order to perform this repair. Depending on the model in question, the center console may need to be removed and subsequently reinstalled. Once repair work is complete, basic setting of the motor/flap controller will need to be carried out.

The necessary spare parts and further information are available from the Peugeot dealer in question.