

Peugeot 307 / 308 / - Funktionsfejl i lygtesystemet | HELLA

Peugeot 307 / 308 / Expert Årgang: 11/2006 - 03/2008 Funktionsfejl i lygtesystemet Lyskontaktens stilling registreres ikke i ovennævnte modeller kan det i enkelte tilfælde forekomme, at lyskontaktens stilling ikke registreres af styreelektronikken. I så fald tændes lygterne ikke som følge af en defekt software. Reparationsanvisning Bilfabrikanten har allerede taget sig af problemet, og brugerne af de berørte biler er underrettet. Problemet afhjælpes ved, at værkstedet foretager en software-opdatering af de berørte biler. Det må antages, at ikke alle biler evt. er kontrolleret hhv. repareret.

307 / 308 / Expert

Year of manufacture: 11/2006 – 03/2008

Malfunction of the lighting system

The light switch position is not being detected

The light switch position in the above vehicles may not be detected by the control electronics in certain cases. If this happens, the lighting system may not switch on due to faulty software.

Repair note

The vehicle manufacturer has already addressed the issue and notified the owners of all the affected models.

To remedy the above problem, the software needs to be updated at the relevant vehicles by a specialist garage.

For various reasons, it can be assumed that not all vehicles may have been inspected or repaired.