

Renault Espace IV - Fartpiloten holder ikke den indstillede hastighed | HELLA
RenaultEspace IV
Motor: 2,0 Turbo
Motorcode: F4Rt alle modeller
Årgang: 2006 - 2010
Fartpiloten holder ikke den indstillede hastighed Hvis ovenstående fejl konstateres, kan det skyldes en ukorrekt software (motorstyreenhed). Efter indstilling af fartpiloten på den ønskede hastighed, holdes den ikke konstant under kørslen.
Reparationsanvisning
For at udelukke andre mulige fejlårsager bør man foretage elektriske og mekaniske systemtests (efter bilfabrikantens anvisninger) samt foretage en udlæsning af fejlhukommelsen med et egnet diagnoseapparat. Hvis der ikke er diagnosticeret fejl, og der ikke er gemt fejlkoder i motorstyreenheden, er det nødvendigt at foretage en softwareopdatering af motorstyreenheden. Derefter bør der foretages en prøvekørsel for at kontrollere, at reparationen er udført korrekt.
BEMÆRK: Vær i den forbindelse opmærksom på, at disse arbejder kun bør udføres af et autoriseret værksted, og at køretøjsfabrikantens reparations- og vedligeholdelsesanvisninger skal overholdes!

Espace IV

Engine: 2.0 Turbo

Engine code: F4Rt for all models

Model year: 2006 - 2010

Cruise control does not maintain the specified cruising speed

If the above-mentioned problem is detected, one possible cause may be faulty software (engine control unit).

Despite programming the cruise control system to the desired cruising speed, this speed is not permanently maintained while driving.

Repair notes

In order to exclude other possible causes of malfunctioning, electrical and mechanical system tests (according to vehicle manufacturer specifications) and also an error code query using a suitable diagnostic unit should all be carried out.

If no errors are diagnosed and error codes are not stored in the engine control unit, a software update of the engine control unit is necessary and should be performed.

Finally a test drive should be undertaken in order to run a check on the repair work.

IMPORTANT:

Please note that such repair work should only be carried out by an authorized specialist workshop and that the vehicle manufacturer's repair and maintenance instructions are to be observed!