

Subaru Forester - Pludselig øget tomgangshastighed | HELLA

Subaru Outback Årgang: 2001 - 2003 Forester Årgang: 2003 - 2004 Pludselig øget tomgangshastighed Hvis der for ovennævnte modeller klages over forhøjet tomgangshastighed, kan det skyldes en defekt i servomotoren i fartpiloten. Evt. kan kablet fra fartpilotens servomotor til gasspjældet løsne sig fra føringen. Det kan forårsage forhøjet tomgangshastighed. Bilfabrikanten har allerede taget sig af problemet, og brugerne af de berørte biler er underrettet. På værkstedet fikseres kablet med en ekstra klemme, hvorved det forhindres, at kablet kan løsne sig. Man må dog af diverse grunde gå ud fra, at ikke alle biler er blevet kontrolleret eller udbedret.

Outback

Model year: 2001–2003

Forester

Model year: 2003–2004

Sudden fast idle speed.

If a sudden fast idle speed is determined in the vehicles listed above, the cause may be a fault in the cruise control system's servomotor.

The control cable from the cruise control system's servomotor to the throttle blade may come loose from its routing. This may result in a fast idle speed.

The vehicle manufacturer has already addressed the issue and notified owners of affected models.

The affected control cable is fixed in position with an additional routing clip at specialist garages, thus preventing it from coming loose.

For various reasons, however, it must be assumed that not all vehicles have been checked or modified.