

Toyota Prius - Overbelastning af hybrid-styreelektronikken | HELLA

Toyota Prius Årgang: fra 2009 Overbelastning af hybrid-styreelektronikken I ovennævnte modeller kan nødprogrammet blive aktiveret efter kraftige accelerationer. Som følge af for kraftige reaktioner ved accelerationer kan hybrid-styreelektronikken blive overbelastet, hvorved bilen skifter til nødprogram. Bilfabrikanten har allerede taget sig af problemet, og brugerne af de berørte biler er underrettet via en serviceaktion. Det må antages, at flere årsager kan have medført, at ikke alle biler er kontrolleret hhv. repareret. Mærkeværkstederne foretager en software-opdatering af de berørte biler.

Prius

Model year: from 2009 onwards

Overload in the hybrid control electronics

On the above vehicles, the emergency program may be activated following heavy acceleration.

Due to excessive acceleration, the hybrid control electronics may become overloaded, causing the vehicle to switch to the emergency program.

The vehicle manufacturer has already addressed the issue and notified the owners of all the affected models of the service operation.

For various reasons, however, it can be assumed that not all vehicles have been inspected and repaired.

The specialist garage will perform a software update on the affected vehicles.