

Volkswagen Golf IV - Air recirculation function | HELLA

Volkswagen

Golf IV

With manual temperature control

Air recirculation function

The above vehicles can experience a supposed failure of the air recirculation function.

The indicator light in the air recirculation switch (figure) can fail prematurely in the above vehicles. This mistakenly leads to the assumption that there is an electrical fault in the switch.

Before replacing the switch or carrying out extensive troubleshooting, the light bulb should be checked or replaced to make sure it works.



The reprinting, distribution, reproduction, exploitation in any form and disclosure of the contents of this document, even in part, is prohibited without our express written approval and indication of the source. The schematic illustrations, figures and descriptions are for explanation and presentation of the document text and cannot be used as a basis for installation or design. All rights reserved.