

Volvo S60 - Defekt olietryksensor | HELLA

VolvoS60Motor: FemcylindretÅrgang: 22.06.2010 - 14.05.2012Defekt olietryksensorI ovennævnte modeller afgives der ikke nogen advarsel ved for lav oliestand på grund af en formentlig defekt olietryksensor.En for lav oliestand kan medføre, at motoren pludselig dør under kørslen (det medfører en betydeligt forøget ulykkesrisiko).Bilfabrikanten har allerede taget sig af problemet, og brugerne af de berørte biler er underrettet.Det må antages, at flere årsager kan have medført, at ikke alle biler er kontrolleret hhv. repareret.På de autoriserede værksteder afhjælpes fejlen ved, at der foretages en software-opdatering af de berørte biler.

S60

Engine: five-cylinder

Model year: 2010-06-22 - 2012-05-14

Defective oil pressure sensor

Probably due to a defective oil pressure sensor, no warning message is issued when the oil level is low in the above vehicles.

If the oil level is too low, the engine may stall suddenly during driving (this significantly increases the risk of an accident).

The vehicle manufacturer has already addressed the issue and notified the owners of all the affected models.

For various reasons, however, it can be assumed that not all vehicles have been inspected and repaired.

The specialist garage will perform a software update on the affected vehicles in order to remedy the issue.