

Volvo XC 90 II - Temperaturregulering af klimaanlæg | HELLA

VolvoXC 90 II (256)Årgang: 2016 - 2017Temperaturregulering af klimaanlægFejl i display for udetemperaturVed ovennævnte biler er der risiko for, at udetemperaturen i kabine-displayet vises forkert. Det kan bevirke, at reguleringen af klimaanlægget også påvirkes negativt. Årsagen kan være en defekt sensor i sidespejlet.For at løse problemet skal udetemperatur-sensoren udskiftes (i huset til det højre sidespejl) med en modificeret variant.Modeller med følgende stelnummer kan være ramt:00000561 - 0143824 og 0042202 - 0143824

XC 90 II (256)

Model year: 2016 - 2017

Temperature control of air-conditioning system

Faulty display for outside temperature

The vehicles mentioned above may have a faulty interior display for the outside temperature. This can also affect how the air-conditioning system is controlled. A faulty sensor in the outside mirror is the possible cause.

To fix the problem, the outdoor temperature sensor (in the housing of the right outside mirror) should be replaced with a modified version.

Vehicles with chassis numbers in the following range may be affected:

00000561 - 0143824 and 0042202 - 0143824