

VW Caddy - Kraftig støj fra motorrummet | HELLA

VWCaddyÅrgang: 2010 - 2015Motor: CBZBKraftig støj fra motorrummetHvis der konstateres kraftig (skinger) støj fra motorrummet, kan årsagen være en funktionsfejl i højtrykspumpen.I dette tilfælde kan støjen skyldes en fejlbehæftet software i motorstyreenheden.Afhjælpning:For at udelukke andre fejlkilder skal der først foretages en kontrol af periferien (højtrykspumpe, etc.) for systemet. Hvis der ikke konstateres fejl her, skal softwaren i motorstyreenheden opdateres.I så fald skal man henvende sig til et autoriseret værksted.

Caddy

Model Year: 2010 – 2015

Engine: CBZB

Loud noise in the area of the engine compartment

If loud (shrill) noises are heard coming from the engine compartment, a possible cause could be a malfunctioning of the high-pressure pump.

In such cases defective software for the engine control unit can be responsible for the noise generation.

Remedy:

In order to exclude other sources which might be causing the problem, first check the system's periphery (high-pressure pump etc.). If no faults are detected here, a software update of the engine control unit is required.

Please contact an authorized specialist workshop for this to be carried out.