

VW Tiguan - Lygterne slukker under kørslen| HELLA

VWTiguanÅrgang: 01/2008 – 07/2011Lygterne slukker under kørslenFor ovennævnte modeller kan det forekomme, at alle lygterne eller en del af lygterne slukker under kørslen.Årsagen til problemet kan være en defekt smeltesikring i kredsløbet til lygterne.Bilfabrikanten har allerede taget sig af problemet, og brugerne af de berørte biler er underrettet.Det må antages, at flere årsager kan have medført, at ikke alle biler er kontrolleret hhv. repareret.På de autoriserede værksteder udskiftes den defekte smeltesikring i de berørte biler med en forbedret sikring.

Tiguan

Model year: 01/2008-07/2011

Light failure while driving

The above vehicles may suddenly experience a partial or total failure of their lighting equipment while driving.

This problem may be caused by a defective fuse in the vehicle lighting circuit.

The vehicle manufacturer has already addressed the issue and notified the owners of all the affected models.

For various reasons, however, it can be assumed that not all vehicles have been inspected and repaired.

The specialist garage will replace the defective fuse with an improved one on the vehicles in question.