

Ford Focus C-Max - Loss of refrigerant | HELLA

Ford

Focus C-Max

Model years: 2003 – 2008

Engine: 1.8 + 2.0 Duratec-HE

Loss of refrigerant

With the above vehicles loss of refrigerant may occur if air-conditioning system lines are broken or cracked.

If it is found during maintenance of the air-conditioning system that the quantity of refrigerant lost is significant, the air-conditioning system lines and their fixings/holders should be closely inspected. Oscillations and vibrations can cause holders to break or lines to crack. Line connections may also start to leak.

When replacing the lines, it should be ensured that they are installed free of stress and with as little oscillation as possible.

Damaged fixings/holders must be replaced at the same time.