

Mazda 3 / 6 / CX5 - Air-conditioning system not performing | HELLA

Mazda

3 / 6 / CX5

Model year: 2013 - 2016

Air-conditioning system not performing

Loss of refrigerant

The air-conditioning system of the vehicles mentioned above may experience a loss in performance. Sometimes there is no refrigerant left in the system.

A faulty evaporator could be a possible cause. Before replacing it with a new evaporator, it should, however, be double-checked that the refrigerant loss is actually caused by this part.

One way of doing this is to fill the air-conditioning system with test gas. With the help of an electronic leak detector,

all pipes and connections can then be checked for leaks.

This information applies to the following vehicles:

Mazda 3 up to chassis no.: JMZBMxxxxxx329072

Mazda 6 up to chassis no.: JMZGJxxxxxx355219

Mazda CX-5 up to chassis no.: JMZKExxxxxx501683