

# Opel Astra H - Engine power loss | HELLA

Opel

All models with a turbocharger

## Engine power loss.

If on these vehicles there are complaints that the engine jerks, experiences loss of power and the error rate P1106 is stored in the engine control unit, it is possible that the cause of failure is a defective or faulty atmospheric pressure sensor.



| kPa      | mV         | 0 - + |
|----------|------------|-------|
| 15 - 117 | 580 - 4750 |       |

