



Seat Altea - water ingress on the side direction indicators

Data sheet	
Manufacturer	Seat
Vehicle model	Altea
Engine	All models
Year of manufacture	Years of manufacture from 2010 onwards
Please note	Model with side direction indicator (halogen)
Symptoms	Water ingress on the side direction indicators

Important safety note

Seat Altea - water ingress associated with the formation of considerable amounts of condensation

If the above-mentioned defect is detected, it may be related to the-build-up of considerable amounts of condensation in the side direction indicators.

If the above-mentioned defect is detected, it may be related to the-build-up of considerable amounts of condensation in the side direction indicators.

In such a case, you should proceed as follows: • Check direction indicator for any damage; if damaged, replace • Position O-ring correctly on the bulb fitting. • Finally make sure that the side direction indicator is properly installed.

 IMPORTANT

This defect may also affect other vehicle models of the same type from this manufacturer.

Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval; indication of the document source is also required. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.