

Skoda Fabia II - Falla el funcionamiento del piloto intermitente lateral | HELLA

Skoda

Skoda Fabia II

Año de fabricación: 2007 - 2014

Falla el funcionamiento del piloto intermitente lateral

Si en el vehículo arriba mencionado (imagen 1) se detecta un fallo en la función del piloto intermitente lateral (imagen 2), puede deberse a una avería en el cable de conexión.




Abb. 1

Imagen 1



Abb. 2

Imagen 2



- Para el análisis de fallos, desmontar la rueda y el revestimiento del tambor de la rueda. Reparar adecuadamente el cable defectuoso. A continuación, asegurarse de que el cable se coloca correctamente (observar si es necesario protegerlo de cantos afilados).

- Comprobar el fusible y sustituirlo en caso necesario.

Comprobar su funcionamiento (imagen 4).



Comprobar su funcionamiento (imagen 4)

Important safety notice

The following technical information and tips for practical use have been set up by HELLA in order to offer professional support to automotive workshops in their daily work. The information available here on this website is only to be used by appropriately trained specialist staff.

The reprinting, distribution, reproduction, exploitation in any form and disclosure of the contents of this document, even in part, is prohibited without our express written approval and indication of the source. The schematic illustrations, figures and descriptions are for explanation and presentation of the document text and cannot be used as a basis for installation or design. All rights reserved.