

VW Passat - Efecto de frenado insuficiente o amplificación de la fuerza de frenado deficiente | HELLA

VW Passat

Fecha de fabricación: 04.2015 hasta 10.2015

Todos los vehículos con «protección previsor para peatones»

Efecto de frenado insuficiente o amplificación de la fuerza de frenado deficiente

Si se detecta el defecto mencionado arriba, una posible causa puede ser un componente ESC deficiente para el control eléctrico de estabilidad. Los pistones defectuosos o adheridos impiden una generación o supresión de presión controlada en el sistema de frenos hidráulico. Ya que para esta unidad hidráulica no hay prevista ninguna reparación por parte del fabricante del vehículo, el componente debe sustituirse por completo.

Repair notes

The vehicle manufacturer has already addressed the issue and notified the owners of affected vehicles. However, it can be assumed that not all vehicles have been inspected and repaired as part of the corrective action.

In case of repair, we recommend contacting an authorized dealer first for coordinating repair handling.