

Peugeot-307-Allumage du témoin d'avertissement ABS | HELLA

Peugeot

Modèle: 307

Année de fabrication: à partir de 2006

Tous les modèles avec ABS/ESP

Allumage du témoin d'avertissement ABS

Code de défaut: 53768

Communication CAN défectueuse

Si l'erreur mentionnée ci-dessus est détectée en combinaison avec un allumage du témoin d'avertissement ABS, cela peut résulter d'une tension d'alimentation défectueuse sur le calculateur ABS/ESP.

Dans ce cas, vérifiez la tension d'alimentation, les connexions ainsi que le câblage sur le calculateur ABS.

Important safety note

Technical information and practical tips have been compiled by HELLA in order to provide professional support to vehicle workshops in their day-to-day work. The information provided on this website is intended for use by suitably qualified personnel only.

Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval and indication of the source. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.