

# Skoda Fabia II - Dysfonctionnement ; feu clignotant latéral | HELLA

Skoda

Skoda Fabia II

Années de fabrication: 2007 - 2014

## Dysfonctionnement ; feu clignotant latéral

En cas de détection d'une panne du feu clignotant latéral ou répétiteur de clignotant (fig. 2) sur le véhicule susmentionné (fig. 1), un câble défectueux peut être en cause.




Abb. 1

Fig. 1



Abb. 2

Fig. 2



- Pour l'analyse des défauts, déposer la roue et l'habillage du passage de roue. Réparer le câble défectueux de manière appropriée. Poser ensuite le câble correctement (le cas échéant, prévoir une protection des arêtes).
- Contrôler le fusible, le remplacer si nécessaire.
- Effectuer un contrôle fonctionnel.(fig. 4).



Effectuer un contrôle fonctionnel (fig. 4).

### **Important safety notice**

The following technical information and tips for practical use have been set up by HELLA in order to offer professional support to automotive workshops in their daily work. The information available here on this website is only to be used by appropriately trained specialist staff.

The reprinting, distribution, reproduction, exploitation in any form and disclosure of the contents of this document, even in part, is prohibited without our express written approval and indication of the source. The schematic illustrations, figures and descriptions are for explanation and presentation of the document text and cannot be used as a basis for installation or design. All rights reserved.