

Alfa Romeo 159 - ABS solenoid valve

Alfa Romeo

159 (Type 939)

All models up to VIN 7097552

ESP indicator lamp lights up

Error code C1275

ABS solenoid valve

If the error code listed above is discovered together with an illuminated ABS indicator lamp, this may be due to faulty software evaluation in the control unit.

First of all, check the power supply and the peripheral equipment of the ABS/ESP system. If all the test results correspond to the targets, the ABS/ESP control unit is the probable cause and should be replaced.

Repair note

In some cases, it may be possible to update the software. If this is the case, please contact an authorized dealer.