

VW Passat - Insufficiente azione frenante o ridotto aumento della forza frenante | HELLA

VW Passat

Anno di costruzione: dal 04.2015 al 10.2015

Tutti i veicoli con "Protezione previdente dei pedoni"

Insufficiente azione frenante o ridotto aumento della forza frenante

Qualora si stabilisca il guasto sopraindicato, una possibile causa è riconducibile all'unità ESC difettosa per il controllo elettronico della stabilità. Pistoni difettosi o bloccati impediscono il controllo della generazione e della riduzione della pressione nell'impianto frenante idraulico. Poiché il costruttore del veicolo non prevede la riparazione dell'unità idraulica, occorre sostituire l'intero componente.

Repair notes

The vehicle manufacturer has already addressed the issue and notified the owners of affected vehicles. However, it can be assumed that not all vehicles have been inspected and repaired as part of the corrective action.

In case of repair, we recommend contacting an authorized dealer first for coordinating repair handling.