

Hyundai IX 35 - El motor no arranca | HELLA

Hyundai

IX 35

Fecha fabricación: 03/2011

El motor no arranca

El motor de arranque no funciona

No se registran fallos en la unidad de control

Si se detecta la problemática arriba mencionada, puede deberse a una avería en el interruptor del pedal de embrague.




Fig. 3



Fig. 1




Fig. 2

ⓘ Important safety notice

The following technical information and tips for practical use have been set up by HELLA in order to offer professional support to automotive workshops in their daily work. The information available here on this website is only to be used by appropriately trained specialist staff.

The reprinting, distribution, reproduction, exploitation in any form and disclosure of the contents of this document, even in part, is prohibited without our express written approval and indication of the source. The schematic illustrations, figures and descriptions are for explanation and presentation of the document text and cannot be used as a basis for installation or design. All rights reserved.