

Mercedes C-klasse - ABS/ESP controlelampje gaat branden | HELLA


Mercedes

C-klasse (W 203)

Alle voertuigen vanaf bouwjaar 02-03

ABS/ESP controlelampje gaat branden

Wordt de bovenstaande storing door de klant gemeld, kan een gecorrodeerde stekkerverbinding hiervan de oorzaak zijn. Verder kunnen foutcode C1140 (stuurhoeksensor, verkeerd signaal) en C1145 (ABS0wielsensor VR, onderbreking) zijn vastgelegd.



Important safety note

The following technical information and tips for practical use have been set up by HELLA in order to offer professional support to automotive workshops in their daily work. The information available here on this website is only to be used by appropriately trained specialist staff.

The reprinting, distribution, reproduction, exploitation in any form and disclosure of the contents of this document, even in part, is prohibited without our express written approval and indication of the source. The schematic illustrations, figures and descriptions are for explanation and presentation of the document text and cannot be used as a basis for installation or design. All rights reserved.