

Peugeot 307 - ABS-waarschuwinglamp brandt | HELLA

Peugeot

Model: 307

Bouwjaar: vanaf 2006

Alle modellen met ABS/ESP

ABS-waarschuwinglamp brandt

Storingscode: 53768

CAN-communicatie foutief

Als de hierboven genoemde fout in samenhang met een brandend ABS-waarschuwinglampje wordt vastgesteld, kan een mogelijke oorzaak een defecte voedingsspanning in het ABS/ESP-regelapparaat zijn.

Controleer in dit geval de voedingsspanning, stekkerverbindingen en bekabeling aan het ABS-regelapparaat.

Important safety note

Technical information and practical tips have been compiled by HELLA in order to provide professional support to vehicle workshops in their day-to-day work. The information provided on this website is intended for use by suitably qualified personnel only.

Reprinting, distribution, reproduction, exploitation in any form or disclosure of the contents of this document, even in part, is prohibited without our express, written approval and indication of the source. The schematic illustrations, pictures and descriptions serve only for the purposes of explanation and representation of the instructions and cannot be used as a basis for installation or assembly work. All rights reserved.