

Hyundai i30 — Avaria prematura das lâmpadas | HELLA

Hyundai i30 Ano de fabrico: 2007–2012 Avaria prematura das lâmpadas
Nos veículos supracitados, pode ocorrer a avaria prematura das lâmpadas dos faróis principais. Os problemas podem dever-se a picos de tensão na rede de bordo elétrica. Primeiro, deve-se verificar a tensão de saída do alternador. Se esta estiver em conformidade com as especificações do fabricante, é possível montar um estrangulador de picos de tensão. Este estrangulador “filtra” os picos de tensão e prolonga a vida útil das lâmpadas. Mais informações podem ser obtidas junto da oficina autorizada.

i30

Model year: 2007 - 2012

Premature light source failure

The aforementioned vehicles may experience premature failure of the light source for the headlamps.

This may be caused by voltage peaks in the vehicle electrical system. Before proceeding further, the output voltage of the alternator should be checked. If this matches the vehicle manufacturer's specifications, a "voltage peak throttle" can be installed.

This "filters out" the voltage peaks and helps to extend the service life of the light source.

For more information, please contact your authorized garage.