

Audi Cabriolet — Rendimento luminoso insuficiente | HELLA

AudiCabrioletAno de fabrico: 2003–2004Com faróis de xénonRendimento luminoso insuficienteNos veículos supracitados, é reclamado um rendimento luminoso reduzido ou insuficiente dos faróis principais.A causa do problema supracitado reside num defeito no revestimento dos refletores dos faróis.O fabricante do veículo já identificou este problema e informou os proprietários dos veículos afetados. No entanto, deve ter-se em consideração que, por diversos motivos, nem todos os veículos foram verificados ou reparados.Na oficina especializada, os refletores dos faróis defeituosos nos veículos afetados são substituídos.

Cabriolet

Model year: 2003 – 2004

With xenon headlamps

Insufficient light output

On the vehicles mentioned above, customers have complained that the headlamps produce a reduced and insufficient light output.

The reason for this problem is a faulty coating on the headlamp reflectors.

The vehicle manufacturer has already addressed the issue and notified the owners of all the affected models. For various reasons, however, it must be assumed that not all vehicles have been checked or modified.

When the affected vehicles are taken to a specialist garage, the faulty headlamp reflectors are replaced with new ones.