

Opel Insignia — Código de erro: C1221, C1222, C1223, C1224 | HELLA

Opel Insignia Ano de fabrico: 2010–2011 A luz de controlo do motor acende Código de erro: C1221, C1222, C1223, C1224 Equivalente a: Sinal de entrada dos sensores de rotação igual a 0. Se os códigos de erro estiverem associados ao problema acima, tal pode indicar um erro no software do módulo de comando. De acordo com o fabricante do veículo, este problema pode ser resolvido através da programação do módulo de comando do motor com software revisto e melhorado. A atualização do software só pode ser efetuada por um concessionário autorizado.

Insignia

Model year: 2010 - 2011

Engine warning light comes on

Error code: C1221, C1222, C1223, C1224

These mean that the input signal of the speed sensors is 0.

If the error codes can be linked with the above-mentioned problem, this could point to faulty control unit software.

According to the vehicle manufacturer, the situation can be remedied by programming the engine control unit with revised and improved software.

Such updating of software is only to be carried out by an authorised dealer.