

Peugeot 307/308— Falha de funcionamento do sistema de iluminação | HELLA

Peugeot 307/308/Expert Ano de fabrico: 2006/11–2008/03 Falha de funcionamento do sistema de iluminação Posição do interruptor de luz não é identificada Nos veículos supracitados, é possível que a posição do interruptor das luzes não seja identificada pela eletrónica de comando. Neste caso, o sistema de iluminação não é ativado devido a um erro no software. Aviso de reparação O fabricante do veículo já identificou este problema e informou os proprietários dos veículos afetados. Na oficina especializada, é realizada uma atualização do software dos veículos afetados, a fim de resolver o problema. No entanto, deve ter-se em consideração que nem todos os veículos foram verificados ou reparados.

307 / 308 / Expert

Year of manufacture: 11/2006 – 03/2008

Malfunction of the lighting system

The light switch position is not being detected

The light switch position in the above vehicles may not be detected by the control electronics in certain cases. If this happens, the lighting system may not switch on due to faulty software.

Repair note

The vehicle manufacturer has already addressed the issue and notified the owners of all the affected models.

To remedy the above problem, the software needs to be updated at the relevant vehicles by a specialist garage.

For various reasons, it can be assumed that not all vehicles may have been inspected or repaired.