

# **Volvo XC 90 II — Regulação de temperatura do ar condicionado | HELLA**

**Volvo XC 90 II (256)** Ano de modelo: 2016–2017  
Regulação de temperatura do ar condicionado  
Indicação incorreta da temperatura exterior  
Nos veículos supracitados, existe a possibilidade de uma indicação incorreta da temperatura exterior no ecrã do habitáculo. Essa mesma falha pode também influenciar o funcionamento correto do sistema de ar condicionado. A causa desse erro pode dever-se a um sensor com defeito, localizado no espelho retrovisor exterior. Para resolver o problema deve-se substituir o sensor da temperatura exterior (alojado na carcaça do espelho retrovisor externo direito) por uma variante modificada. Este problema pode afetar os veículos com os seguintes VIN: 00000561–0143824 e 0042202–0143824

## **XC 90 II (256)**

**Model year: 2016 - 2017**

### **Temperature control of air-conditioning system**

#### **Faulty display for outside temperature**

The vehicles mentioned above may have a faulty interior display for the outside temperature. This can also affect how the air-conditioning system is controlled. A faulty sensor in the outside mirror is the possible cause.

To fix the problem, the outdoor temperature sensor (in the housing of the right outside mirror) should be replaced with a modified version.

Vehicles with chassis numbers in the following range may be affected:

00000561 - 0143824 and 0042202 - 0143824