

VW Crafter - Auxiliary battery is not charging | HELLA

VW

Crafter

Model year: 2011

With auxiliary battery

Auxiliary battery is not charging

In the above vehicles, incorrect coding of the electric system control unit may be the cause that the auxiliary battery is not charging.

To remedy this, the electric system control unit must be re-coded.

The vehicle manufacturer has already addressed the problem. Nevertheless, one may assume that for various reasons not all vehicles have been checked and repaired.

Please note this information in connection with complaints regarding an auxiliary battery that is not charging.